

Laser Cutting

HIGHEST QUALITY, BEST ACCURACY



Basically when cutting with the laser the beam is focused on the material through the hole in the nozzle. This heats the material and melts it. A cutting gas, which flows co-axially through the nozzle, removes the molten material. Due to the small focus spot, laser cutting is known for its high accuracy.

The laser cutting process uses a strong focused laser beam. The high energy laser beam heats up the material. During the cutting process, an assistant gas is used to eject the molten material from the kerf. As a result, the cut quality and speed are very high compared to other cutting technologies.

You can choose between two basic types:

Flame (oxygen cutting), is characterised by the fact that the material is only heated to its ignition temperature. Oxygen is used as cutting gas, so that the material burns and forms an oxide which melts through the additional energy from burning. The cutting Oxygen then forces the slag out of the cut. Typical material is, for example, low alloy steel (mild steel).

For fusion cutting, the material is melted directly by the laser beam. As with sublimation cutting, an inert gas, usually Nitrogen, is also used here to force the molten material out of the cut. This process is typically used for alloyed steels (Stainless Steel).

Laser Cutting

All processes have in common that, because of the narrow focus of the laser beam, the width of cut (kerf width) is very small compared to the other thermal cutting processes. Thus minimum material is melted and the laser energy is used very efficiently. The heat input into the material is thus relatively low so that even small geometries can be cut. In addition, the cut edge is relatively straight which in all gives very high component accuracy from the cutting process.

This means that laser cutting is used in the most diverse areas, specifically wherever high accuracy for the component geometry and the cut edge is required. The preferred range for steel sheets is up to a material thickness of 20 mm, under certain circumstances up to 25 mm. For this application mainly the CO₂ Laser and Fiber Laser are used. For greater thicknesses, laser cutting only makes sense for special applications, more usually other cutting processes (oxyfuel or plasma cutting) are used here.

In order to even get more flexibility, laser cutting can be combined with plasma cutting also.

CHARACTERISTICS:

- Plate thickness: 1 mm up to 25 mm
- Typical: 0.5 mm up to 20 mm

KEY FEATURES:

- Laser light can be well focused ca. 0.2 mm
- Laser radiation: coherent, monochromatic, high energy
- Very high power density (some MW/cm²)
- High to medium cut quality (roughness)
- Metallurgical perfect surfaces (oxidized) or metallically blank surfaces (high pressure inert gas cutting)
- Low heat input Hardening within the area of the heat-affected-zone (HAZ) with hardening (HAZ) (small)
- Dust as well as UV and IR-radiation

